



LOCAL NOTICE TO MARINERS No 25 OF 2015

CHANGE TO TIDAL FLOWS IN COWES HARBOUR

(This notice supersedes LNTM No. 8 of 2015 which is hereby cancelled)

Tidal flow modelling carried out before construction of the breakwater predicted certain changes to the tidal rates and directions within the harbour. This notice provides the latest observed changes to the tidal system at Mean High Water Springs (4.2m). Tides above MHWS may result in higher tidal flows than predicted. All harbour users should take these tide flows into account when navigating in the harbour.

1. Inner Fairway west of the breakwater

When the tidal flow at Nos. 1 and 2 fairway buoys is running in a westerly direction, (expected from HW -2hrs to HW +3hrs) a tidal shadow with significantly reduced flow will be experienced immediately west and south of the breakwater in the Inner Fairway.

2. Inner Fairway between the Island Sailing Club and the Small Craft Channel (Fig 1)

Between HW -2.5hrs and HW -1hr, in addition to the tidal shadow west and south of the breakwater, vessels transiting the Inner Fairway between the Island Sailing Club and the Small Craft Channel will experience a westerly setting tidal flow of up to 1.5knots which will have a tendency to set vessels down towards the western shore. This cross current splits into two separate flows on the western side of the fairway in between the Island Sailing Club and the Red Jet terminal with a current of up to 1.5knots running along the foreshore in either direction.

Small craft should be prepared to alter their heading so as not to be set across the fairway when transiting this area and avoid impeding the safe passage of commercial shipping and ferries.

Large vessels entering or leaving the harbour during this period must be aware that due to the westerly going tide at Nos. 1 and 2 buoys, the significant reduction in tidal flow in the shadow of the breakwater and a possible westerly going tide in the Inner Fairway between the Island Sailing Club and the Small Craft Channel, that when the vessel crosses the boundaries of these areas the differing tidal flows may induce a turning moment.

All vessels will have a tendency to be set down towards the western shore when within the westerly tidal streams. All mariners are instructed to navigate with particular caution in the vicinity of the harbour entrance and Inner Fairway.




Fig 1: Typical cross current south of the breakwater HW -2hrs at MHWS

This Local Notice to Mariners remains in force until further notice.

Stuart McIntosh

Harbour Master, Harbour Office, Town Quay, Cowes, Isle of Wight, PO31 7AS

Email: chc@cowes.co.uk

Internet: www.cowesharbourcommission.co.uk

22nd July 2015